

RICH N2 Auto Change Test Setup Components		
RV1	Control Devices STLMO ST25 1/4 NPT, CRN0G8703.5C G0, 75psi/74scfm	75 psi
MV1	1/4: ball valve, RUB inc. #CW617N	400 psi
MV2	Weksler, BBV4, needle valve, granger 5WL12	600 psi
CV1	Swagelok, SS-4CP2-1/3	1500 psi
PI1	Winters, PFQ710LF, 0-60 psi gauge, granger 36TW10	
PI2	Winters, PFQ710LF, 0-60 psi gauge, granger 36TW10	
PV1	Air operated poppet valve, Swagelok, SS-92M4	450 psi wp
PR1	Control Air type 700, 0-30 psi, 80 scfm	250 psi
PT1	Dwyer 0-50 psi absolute pressure, 626-02-GH-P1-E1-S1	600 psi
PT2	Dwyer 0-50 psi absolute pressure, 626-02-GH-P1-E1-S1	600 psi
1/2" Nylon Tubing	Parker parflex, NNR-8-062-0050	250 psi wp
1/2" brass tubing inserts	parker tube insert - L63pt-8-62	650 psi
1/4" copper tube	MUELLER, type ACR, 653R	1406 psi
Female Tee	Parker, L2203P-4	1000 psi
needle valve	Weksler, BBV4	600 psi
1" brass nipples	Parker, VS215PNL-4-15	1000 psi
Brass female union	Polyconn, pc103nb-4, nickle plated brass	1000 psi
1/2" port connector	swagelock ss-811-pc	
1/2" comp to 1/4 npt	swagelok ss-810-1-4	
90 degree union	swagelok B-810-9	
union tee	swagelok ss-810-3	
female branch tee	swagelok ss-810-3-4ttf	
1/4" comp to 1/4 npt	swagelok ss-400-1-4	
1/4" comp to 1/8 npt	swagelok ss-400-1-2	