

## **Survey**

Position of the corners of the calorimeter

## **Beam view**

Another survey of the bottom has been done after opening the ECal: maximum difference observed is 0.45 mm (it is the first corner that I fixed).