


C75 Pair 4 Flange Photos (Pair leaking)

29Sep2020



Good morning as discussed I torqued bolts and studs to 120 inch pounds this morning and re-leak checked we had no change in leak rate since 6/27 after re-torque I notice and felt what appears to be the flange bulging out in line with the bolts and studs I have included pics to show what I mean along with from the other dogleg flange that isn't leaking to compare to.



Good morning as discussed I torqued bolts and studs to 120 inch pounds this morning and re-tight checked we had no change in leak rate 210E-05 After the re-torque I notice and felt what appears to be the flange bulging out in line with the bolts and studs I have included pics to show what I mean along with pics from the other dogleg flange that isn't leaking to compare to.