LERF Ocilloscope Status

Kevin Jordan 876-1742 7-Jul-16

	Location	Name	Model	GPIB Connected	Ethernet Connected	Video output	Control Status	Comments
	Orive Laser Clean room		TDS3014C	Yes	Yes	Connected & NOT functioning	Not connected	Video not found
	Orive Laser Clean room	DL SCOPE	TDS3012B	No	No	Connected & NOT functioning	Some functions WORK!	but no video
F	L02B11	TEK SCOPE #1	TDS3012B	No	Yes	Connected & functioning	Page resolved but Not functioning	
F	EL02B11	TEK SCOPE #2	TDS3034B	Yes	Yes	Connected & NOT functioning	Page found but not resolved	GPIB connection is IP PAC on IOCFEL8, page not resolving. The GPIB also connected to HP33220A Arb Fun Gen for the M55 system
F	L02B11	TEK SCOPE #3	TDS3034B	No	Yes	Connected & functioning	Page found but not resolved	
F	L02B11	TEK SCOPE #4	TDS3014B	No	Yes	Connected & functioning	Page found but not resolved	
F	L07B08	TEK SCOPE A	TDS3034B	Yes	Yes	Connected & functioning	Page found but not resolved	From AMS menu, listed incorrectly as TDS754A
F	:L07B08	TEK SCOPE B	TDS3034B	Yes	Yes	Connected & NOT functioning	Page found but not resolved	From AMS menu, listed incorrectly as TDS754A
R	Optics CNTRL Room	OCR SCOPE	TDS3034B	No	Yes	Connected & NOT functioning	Page found but not resolved	From AMS menu, listed incorrectly as TDS3000
	/ault Output coupler	OC SCOPE	Scope remov	ed				From AMS menu, listed as TDS3000