

HALL C PLC TASKS REPORT (08/30/2018 – 09/05/2018)

- NMR unit testing continued.
 - ★ Code added to update DSG-PLC with field and lock status.
- UPS monitoring routines revised.
 - ★ Reset for delay timer added.
 - Resets timer when interlock fault clears.
 - ★ Logic changed for fault reset.