

Hall A	Temp (K)	Notes
Left Q2	55	on cold return
Left Q3	50	on cold return
Left D	52	on warm return
Right Q2	55	on cold return
Right Q3	60	on cold return
Right D	73	on warm return

Hall B

Torus	33	supply shut off
Solenoid	25	supply shut off
Buffer dew	100+	supply shut off

Hall C

HMS Q1	21	On warm return
HMS Q2	4.2	on cold return
HMS Q3	100+	On warm return
HMS D	6.9	on cold return
SHMS HB	200	On warm return
SHMS Q1	5.4	On warm return
SHMS Q2	61	On warm return
SHMS Q3	4.6	On warm return
SHMS D	4.7	on cold return